

## MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

RECEIVED phiss Breath Alcohol Program By Carol Day at 2:19 pm, Sep 02, 2009

Complete this report in duplicate at the time of the regular management of Health; retain original in	nonthly preventive maintenance	check, and whenever instrument	
DATAMASTERSN	Adopartmon mor	DATE OF INSPECTION	
204106 LOCATION OF INSTRUMENT (STREET AND CITY)		8-30-09 TIME OF INSPECTION	
Monroe City Police Department, 300 North Main Street, Mon	roe City, MO 63456	2301	
CHECKLIST: Place a check (4) to the left of each item if found in observed values where determined.) Unchecked items must be	d to be satisfactory or if operation of the corrected before using instrum	ng within established limits. (Write lent.	
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)			
☑ COMPUTER	☑ DETECTOR		
☑ PROGRAM	☑ FILTERS		
☑ HEATERS SAMPLE CHAMBER _50_ °C	2 QUARTZ STANDARD		
☑ FLOW DETECTOR	O CALIBRATION		
☑ PUMP HIGH SPEED	2 PRINTER		
☑ INDICATOR LIGHTS			
☑ TIME AND DATE			
SIMULATOR TEMPERATURE (34 °C ± 0.2°C)			
☑ CALIBRATION CHECK:			
Hun three tests using a standard solution. All three tests must be within $\pm$ 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE			
spread of ,005 or less. Check the box corresponding to the RECIRCULATION PUMP)	e standard solution being used	"(bunton) Vitalouen) (noe	
☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% an	d 0.105% INCLUSIVE		
O.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE  (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)			
TEST 1 .096 TEST 2 .0	97 TEST	3 .098	
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)		-	
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)			
REFUSALS Ø (004) Ø (.0509)	(.10-,14) / (.15-,19)	Z (Over,19) O	
List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily			
and within established limits (use other side if necessary)			
The state of the s			
· · · · · · · · · · · · · · · · · · ·			
Instrument meets Dept. of Health specs., Guth Labs., 10 solution, lot no. 03340, exp. 10-15-09			
INSPECTING OFFICER			
SIGNATURE	PRINT NAME B. C. Griffin		
TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER		
920080 / 04-22-2011	(660) 385-2132	_	



### CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08340 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1211 percent (w/vol) ethyl alcohol. The expiration date for this lot number is October 15, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol. analysis instrument reading of 0.10 percent BAC.

The alcoh and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

#### Face This Side Down - This Edge In First

# BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204106 08/30/09

TESTING OFFICER:
GRIFFIN/BRANDON/C
OFFICER I.D.: 0429
PERMIT NUMBER: 920080
EXPIRATION DATE: 04/22/11
MISCELLANEOUS DATA:

#### --- SUPERVISOR MODE ---

BLANK TEST	. 966	23:14
INTERMAL STANDARD	VERIFIED	23:14
EXTERNAL STANDARD	. 896	23414
BLANK TEST	. 685	23:15
EXTERNAL STANDARD	. 1897	29:15
BLANK TEST	.999	23:16
EXTERNAL STANDARD	. 999	23:16
BLANK TEST	. 806	23:17

M = 3 JIM. = .1 JVG. = .097

#### Face This Side Down - This Edge In First

## **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204106 08/30/09 23:01

-- DIAGNOSTIC CHECK ---

COMPUTER:

delayer of aport

OKAY

FROSRAM (64-87-2609):

OKAY

HEATERS

SAMPLE CHAMBER:

77171

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED:

OKAY

DETECTOR:

OKAY

FILTERS

OKHY

QUARTZ STANDARD:

CHARY

CALIBRATION:

OKAY

PRINTER TEST

!"#\$%&{()\*+,-./0123456789:;{=}70ABCDEFS HIJKLMMOPORSTUVWXYZ[\]~\_^abcdefghijklmno pqrstuvwxyz{|}}+

Operator Signature\_

Printed on recycled paper with agri-based inks

CMSU 2208-02

tor Signature \_\_\_\_

recycled paper with agri-based inks

CMSU 2208-02

Face This Side Down - This Edge In First

de principale de la compresión de la compr La principale de la compresión de la compr

## **BAC** DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204196 09/30/09

MRREST TIME: 22:30 SUBJECT MAME: TEST 208: 01/01/70 SEX: M STHTE/D.L.: MU/1234567890 ARRESTING OFFICER: GRIFFIN/B/C OFFICER 1.D.: 0429 TESTING OFFICERS GRIFF1H/B/C OFFICER I.D.: 0429 PERMIT NUMBER: 920080 EXPIRATION DATE: 84/22/11 MISCELLANEOUS IATA: R.F.I. TEST

--- BREATH AMALYSIS ---

BLANK TEST FINTERNAL STANDARD RADIO INTERFERENCE . 969

23135

VERIFIED

23136

Operator Signature

2208-02

## State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

## PERMIT TYPE II



Lab. 4 (A7-88)

## **BRANDON GRIFFIN**

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

**DATAMASTER** 

# for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986. Date 04/22/09 Pumber 04/22/2011 Expires Director, Department of Health